




A2L Mitigation Wiring with Alarm Contact that Turns ON During Leak

Arzel Technical Support
1-800-611-8312
techsupport@arzelzoning.com



If an A2L refrigerant leak is detected:

- The refrigerant detection system (RDS) board energizes the 24VAC alarm contact
- The relay will be energized
- The Arzel Zoning board will lose power
- The air pump will run continuously.
- All zoning dampers will open

Wire HVAC outputs as if they were connections for a thermostat.